

MATERIAL DATA SAFETY SHEET

PRODUCT NAME : SUPREME

SECTION 1 MANUFACTURER'S INFORMATION

CHEM - TEX DYE AND CHEMICALS 7108 MULLINS
HOUSTON, TEXAS 77081 (713) 668-1212

SECTION 2 HAZARDOUS INGREDIENTS / IDENTIFY

Hazardous Components	OSHA	PEL	TLV	CASE#
Proprietary	N/A		N/A	N/A

CONTAINS : SODIUM METASILICAE, ETHYLENE GLYCOL MONOBUTYL ETHER, AN ALPHA OLEFIN SULFATE, SODIUM SALT, WATER

SECTION 3 PHYSICAL & CHEMICAL CHARACTERISTICS

Boiling Pt. N/A Gravity : 1.01 Vapor press : N/A
Vapor Density : N/A Solubility in H2O : Solubls
Melting Point : None Reactivity in H2O : None
Appearance and Odor : Blue liquid with mild solvent odor

SECTION 4 FIRE & EXPLOSION DATA

Flash Point : N/A Method : Flammable Limits : None
Auto ignition : None Extinguisher Media : Foam, Co2, Dry chemical
Fire Fighting Procedures. Closed drums exposed to fire should be cooled by a water spray to avoid pressure buildup.
Unusual fire / Explosion Hazards : N/A

SECTION 5 PHYSICAL HAZARDS (REACTIVITY DATA)

Stability : None Conditions to Avoid : None
Incompatibility : Strong Oxidizers
Hazardous Polymerization : None

SECTION 6 HEALTH HAZARD

ACUTE : Not Established Chronic : Not Established
EXPOSURE SYMPTOMS : Reddening and Burning Sensation on Skin
MEDICAL CONDITIONS GENERALLY AGGRAVATED : Unknown
LISTED AS CARCINOGEN NLP : NO I.A.R.C. : NO OSHA : NO
EMERGENCY PROCEDURES : See Below

SECTION 6 HEALTH HAZARDS

Acute : Not Established Chronic : Not Established
Exposure Symptoms : Reddening and burning sensation on skin
Medical Conditions Generally Aggravated : Unknown
Listed as Carcinogen NLP : No I.A.R.C : No OSHA : No
Emergency Procedures : See below

INHALATION : Remove victim from contaminated area. Call a physician. If not breathing begin resuscitation.

EYES : Flush eyes with running water for at least 15 minutes. Call a physician.

SKIN : Wash with soap and water. Call a physician if there is any evidence of irritation or burning. Wash clothing before reuse.

INGESTION : Unknown

SECTION 7 SPECIAL PRECAUTIONS (SPILLS AND LEAKS)

HANDLING AND STORAGE : Keep away from heat and flame. Use with adequate ventilation. Avoid exposure to vapors. Direct contact causes irritation of the eyes and skin. Avoid contact with eyes, skin, and clothing. Wash thoroughly.

SPILLS : Dike liquid spills and pump into salvage containers. Powder spills should be gathered up and placed into salvage containers.

DISPOSAL : Incinerate by injection into an open furnace. Disposal must comply with local, state and federal regulations.

SECTION 8 SPECIAL PROTECTION INFORMATION

Use a NIOSH / MESA – approved respirator
Venti